

Firmware Update history

[Nov 21, 2022]

1.0.0 - First release firmware.

[Mar 31, 2023]

1.0.1 - Fixed potential unintended behaviors when exiting Globals/Options menu.

[May 11, 2023]

1.0.2 - Fixed a bug in LFO state toggling routine, which could cause system error when midi clock is reception is active.

[May 19, 2023]

1.0.3 - Improved encoder operation accuracy and robustness.

[June 1, 2023]

1.0.4 - Added 'Gain X' and "Gain Y" functions to Midi CC implementation.

1.0.5 - Added 'Mute L', 'Mute R', and 'Mute LR' functions to Midi CC implementation.

[June 18, 2023]

1.0.6 - Fixed a bug with Midi CC#19 operation.

[June 27, 2023]

1.0.7 - Improved operational stability.

[Sep 18, 2023]

1.0.8 - Fixed bug in the blending operation.

[Jan 8, 2024]

- 2.0.0 - Added Global Dry signal On/Off feature.
 - Added two subdivision values: Whole-2 and Whole-4.
 - Added Random LFO shape.
 - Added two MIDI CC functions: Wet-L (CC#37) and Wet-R (CC#38).

[Jan 10, 2024]

- 2.0.1 - Fixed freezing issue in firmware 2.0.0.

[Feb 5, 2024]

- 2.0.2 - Fixed a bug in "cc_Dry()" function.
 - Fixed freezing issues in series routing mode.